#### WATER NEW ZEALAND ANNUAL CONFERENCE 2017 - HAMILTON

## Ensuring a Safe Future Drinking Water Supply for the Rangitaiki Plains

Shahbaz Sandhu - Environmental Engineer

Jonathan Graham - Water Infrastructure Services Leader

Pattle Delamore Partners Limited (PDP), Tauranga, New Zealand



Hydrogr

Hydroge

other

### INTRODUCTION

- \*Background of the projects
- \*Consents required
- \*Design and challenges faced
- \*Construction and problems encountered
- \*Commissioning



### **EXISTING WATER SOURCES**

- \*Braemar Spring and Johnson Road sources contain elevated levels of Arsenic (0.023 mg/l, 0.018 mg/l and 0.11 mg/l respectively)
- \*Tahuna Road and Johnson Road only have partial barriers to contamination and aren't secure
- \*These sources do not comply with DWSNZ






### **ARSENIC REMOVAL TECHNOLOGIES**

4


\*Coagulation followed by sedimentation, filtration and / or UV treatment

\*G2 Absorbent Media followed by UV treatment



### **AREA OF SERVICE**





### **CONSENTS ACQUIRED**


\*Building and Earthworks consent

\*Land use consent

\*Property consent



### **DESIGN - Paul Road Delivery Pipeline**







### **Bridge Crossings**

#### Rangitaiki Bridge Pipe Crossing


#### Reids Canal Bridge Pipe Crossing








### Paul Road Building



### **Pump Curves**

Bore Pump Curve

**Booster Pump Curve** 




### **CONSTRUCTION ISSUES**

\*Flooding

\* Weather Delayed Programme

\* Soil Type and Compaction Issues

\*Acidic Groundwater Testing





### COMMISSIONING

\*Bore Flushing

\*Water Tank Testing and Pipeline Flushing

\*Disinfection






### Tahuna Road Water Supply Upgrade

- \*A larger capacity bore pump and new high-lift pumps
- \*Two stage cartridge filtration system
- \*New UV unit
- \*Conversion to Chlorine gas
- \*New 31 m3 Plastic Tank



### Tahuna Road Water Treatment Plant



### Tahuna Road Drinking Water Compliance with DWSNZ

\*Bore was raised 500mm above 100 year flood level

\*UV unit provides 3 log credits

\*Cartridge Filtration provides 2 log credits



# \*QUESTIONS

